

Raport de monitorizare - Septembrie 2025

parametru Formaldehidă (HCHO)

la coșul de dispersie - Instalație post-ardere catalitică, *Instalație FORMOX C1.36.1*
în acord cu AIM nr. 11 din 26.10.2011, revizuita la data de 12.07.2021

Data		Media la 24H	Limita conf. AIM nr.11 din 26.10.2011, revizuita la data de 12.07.2021
01.09.2025 00:00	02.09.2025 00:00	0,45	5
02.09.2025 00:00	03.09.2025 00:00	0,44	5
03.09.2025 00:00	04.09.2025 00:00	0,39	5
04.09.2025 00:00	05.09.2025 00:00	0,41	5
05.09.2025 00:00	06.09.2025 00:00	0,48	5
06.09.2025 00:00	07.09.2025 00:00	0,49	5
07.09.2025 00:00	08.09.2025 00:00	0,42	5
08.09.2025 00:00	09.09.2025 00:00	0,38	5
09.09.2025 00:00	10.09.2025 00:00	0,59	5
10.09.2025 00:00	11.09.2025 00:00	0,80	5
11.09.2025 00:00	12.09.2025 00:00	0,82	5
12.09.2025 00:00	13.09.2025 00:00	0,71	5
13.09.2025 00:00	14.09.2025 00:00	0,71	5
14.09.2025 00:00	15.09.2025 00:00	0,77	5
15.09.2025 00:00	16.09.2025 00:00	0,70	5
16.09.2025 00:00	17.09.2025 00:00	0,75	5
17.09.2025 00:00	18.09.2025 00:00	0,83	5
18.09.2025 00:00	19.09.2025 00:00	0,84	5
19.09.2025 00:00	20.09.2025 00:00	0,80	5
20.09.2025 00:00	21.09.2025 00:00	0,81	5
21.09.2025 00:00	22.09.2025 00:00	0,99	5
22.09.2025 00:00	23.09.2025 00:00	1,05	5
23.09.2025 00:00	24.09.2025 00:00	0,99	5
24.09.2025 00:00	25.09.2025 00:00	1,12	5
25.09.2025 00:00	26.09.2025 00:00	1,13	5
26.09.2025 00:00	27.09.2025 00:00	1,05	5
27.09.2025 00:00	28.09.2025 00:00	1,06	5
28.09.2025 00:00	29.09.2025 00:00	-	5
29.09.2025 00:00	30.09.2025 00:00	-	5
30.09.2025 00:00	01.10.2025 00:00	-	5

Obs: In intervalul 28.09.2025, ora 10:18 si 02.10.2025 ora 10:50, Instalatia Formox de pe platforma "Fabricii de adezivi EGGER Technologia" a fost oprita pentru lucrari de intretinere.

PETROȘEL Ovidiu

Administrator
EGGER Technologia S.R.L.

